

Mentone Flying Club, Inc. Newsletter

P. O. Box 938 March 2000

Rochester, IN 46975 Phone 219-223-8736

Internet Address: <http://www.geocities.com/capecanaveral/9231>

Presidents Air Space:

The new door on the north hanger is currently functional. Any member having questions or problems operating the door please contact Bill Willard or myself. When parking at the hangers, please stay off any grass around the hangers. When parking in the field to the east, be sure to park past the mowed area. This will give taxing aircraft's the room they need. When filling out the Hobbs tickets in the aircraft, take time to be sure they are correct. Several tickets have caused concern with other members and extra work for Bill Willard. This seems to be an ongoing problem. If we are hurrying through the post flight, check what could we be missing on the pre-flight.

Aircraft Status:

07V good to go

42U good to go

69T has had a total vacuum pump failure

874 is not carrying the vacuum pressure required. New pumps have been ordered for both aircrafts.

By the time you get this news letter both pumps should be replaced.

We are still missing 3th from 3607V

Club Events:

Club meet is set for Friday, March 17th 1900 hours at the hanger

Watch your airspeed

John Cash

Congratulation there Tom Truong on your private license